

HQT-4180 Actual Questions - Instant Download 37 Questions [Q17-Q33]



HQT-4180 Actual Questions - Instant Download 37 Questions [Q17-Q33]

HQT-4180 Actual Questions - Instant Download 37 Questions Download Free Latest Exam HQT-4180 Certified Sample Questions NO.17 Which program is used to perform the "New Installation" procedure on a VSP midrange system?

- * MPC
- * Webconsole
- * GUM
- * BECK

NO.18 You have to perform a firmware update containing new code for DKCMain, CHBs and drives on a VSP G900.

What are two requirements? (Choose two.)

- * The CHBs must be updated first.
- * The Microprocessor utilization should be below 50%.
- * The Cache Write Pending rate should be below 30%.
- * There should be no sparing processes running in the background.

NO.19 Which two statements are correct when adding cache to a VSP E590? (Choose two.)

- * Cache modules must be installed in CMG1.
- * Cache Modules must be installed on the CM board.

- * CMG0 and CMG1 must have the same DIMM type.
- * This is not supported online.

NO.20 A customer wants to upgrade a VSP G700 to 512 GB RAM capacity.

What is the valid CFM configuration?

- * two BM35 per controller
- * two BM45 per controller
- * one BM45 per controller
- * two BM35 per system

NO.21 What is the recommended RAID level when creating a Hitachi Dynamic Provisioning (HDP) pool?

- * RAID 1
- * RAID 1+0
- * RAID 5
- * RAID 6

NO.22 A customer has a VSP G370 with the encryption license key installed. They now want to have all the DP-Volumes of a certain pool located on encrypted RAID Groups.

What are two requirements? (Choose two.)

- * The controller board must support encryption.
- * The RAID level of RAID Groups in the pool must be RAID 6.
- * At least 20 GB of Shared Memory must be installed.
- * The RAID Groups in the pool must be formatted with encryption enabled.

NO.23 What is the maximum size of a basic volume carved out from an internal parity group on a VSP E590 system?

- * 1 TB
- * 2.99 TB
- * 65 TB
- * 128 TB

NO.24 The SVP of a VSP G900 system failed and you have been asked to replace it.

Which two items must be available to perform the replacement? (Choose two.)

- * the iso file with the correct version of Hitachi Ops Center
- * the iso file with the correct version of the Windows operating system
- * the microcode iso file with the correct software versions
- * the Hitachi Remote Ops Monitor Agent iso file

NO.25 Which tool do you use to install license keys on a VSP G370 system?

- * HSA Embedded
- * MPC Software
- * Storage Navigator
- * Maintenance Utility

NO.26 One Unix server and one Windows server share the front-end ports CL1-A and CL2-A of a VSP E590 system.

What are two requirements to separate the I/Os of the servers? (Choose two.)

- * Both servers must be registered in two different Host Groups.

- * Port security must be enabled on both ports.
- * The Universal Volume Manager license must be installed.
- * Two cache partitions must be created on the VSP for the servers.

NO.27 A customer wants to upgrade their VSP E790 with a SAS Expansion feature.

What are three requirements? (Choose three.)

- * Two additional Disk Boards (DKBs) have to be installed.
- * Slots B of both controllers must be available for DKB installation.
- * The SAS Expansion license has to be installed.
- * In Shared Memory, the Extension1 has to be enabled.
- * Drive Boxes (DBs) with SAS interface have to be added.

NO.28 You need to replace a failing power supply (PS) in a VSP E590.

What is the correct procedure?

- * Check if the status of the PS is blocked, and if yes, then replace it directly.
- * Use the Maintenance Utility for blocking the PS, then replace it.
- * Use the Maintenance Utility for blocking the controller, then replace the PS.
- * Use the MPC for blocking the PS, then replace it.

NO.29 Which two VSP systems support attached Drive Box Flash (DBF)? (Choose two.)

- * VSP E590
- * VSP F370
- * VSP F700
- * VSP G900

NO.30 A customer wants to change a production RAID Group from RAID 5 (7D+1P) to RAID 6 (6D + 2P) on a VSP G700 during normal operations. They have just unmapped the LUNs from the channel ports.

What needs to be performed next?

- * The RAID level must be changed in Storage Navigator.
- * The RAID level must be changed in the SVP Maintenance window.
- * The RAID 5 Group must be put into DRU mode in Storage Navigator.
- * The RAID Group must be deleted.

Free Hitachi HQT-4180 Exam 2023 Practice Materials Collection: <https://www.vceprep.com/HQT-4180-latest-vce-prep.html>